

General Environmental Incident Summary

Incident: 2123

Notice: 11/27/2013 1020

Occurred: 7/9/2013

DEM Incident No:

No Further Action: ☒

Responsible Party: Zimmerman Contracting Inc.

County: Burleigh

Twp Rng Sec Qtr: 139 78 28

Lat Long + Method: 46.83033 -100.53070 Derived from TRS

Location Description: 16134 Andre Loop
Menoken, ND 58558

Submitted By Info: John Ronsberg
3900 Heartland Dr
Bismarck ND 58503

Received By Info:

Contact Info: John Ronsberg
3900 Heartland Dr.
Bismarck ND 58503

Affected Medium:

Near. Occupied Bldg:

Type of Incident: Changing motor oil spill

Release Contained:

Reported to NRC: Unknown

Contaminant: CenexTMS 15w/40 motor oil

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Spill of motor oil while dumping used oil into storage tank for recycling.

Risk Evaluation:

Potential Env. Impacts:

Action Taken/Planned:

Soil excavated, hauled to asphalt plant for disposal
Investigation report completed by Vieau Associates Inc.

Wastes Disposal Location:

Northern Improvement asphalt plant, Bismarck, ND

Other Agencies Involved:

Updates

Date: 11/30/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Notes:

Date of incident vs. date of report needs verification. Spill of used motor oil reportedly cleaned up. Follow-up is necessary to determine details and timeline.

Updated Volume: None at the time of this update

Date: 12/3/2013 **Status:** Correspondence

Author: Miller, Adam

Notes:

Contacted Jon Ronsberg via telephone to ask about date of incident versus date of reporting discrepancy. Jon stated they were going to build a shop on the property and had ordered a Phase II environmental analysis because of oil staining in the area that had resulted from leaked used motor oil over a long period of time. A copy of the Phase II assessment is in the file folder. The incident date was assigned; it was not actually the date the spill occurred. The contaminated soil has been excavated and is scheduled for disposal.

Updated Volume: None at the time of this update

Date: 6/15/2018 **Status:** Inspection

Author: Suess, Bill

Notes:

Building has been constructed and all stockpiled material has been removed. No signs of adverse impacts at site. No photos taken.

Updated Volume: None at the time of this update